

#### FORK MEASURING COMPANY Vavdi Sr.No. 17, Plot No 55B, Rani Industrial Estate Gondal Road, Rajkot-360002

## **INSTRUCTION MANUAL FOR DIGITAL MICROMETER (601-025)**

## > Technical Specification

Code	Range	Least Count
601-025	0-25 mm	0.010 mm
601-050	25-50 mm	0.010 mm
601-075	50-75 mm	0.010 mm
601-100	75-100 mm	0.010 mm
601-125	100-125mm	0.010mm
601-150	125-150mm	0.010mm



## > Operation

- Keys are pressed two ways to execute functions:
  - 1. Press and immediately release.
  - 2. Press and hold for at least two seconds.

# ➢ On/Off⁻ Zero Key

- Press and release: Power on/off
- Press and hold: Zero set for absolute measuring.

# > ABS/INC Unit Key

- Press and release: Absolute and INC measuring mode conversion
- Press and hold: Inch/Metric conversion("in" will appear for inch readings, "mm" will appear for metric readings.

# > Data Output

In measuring mode, this is the data output key.

Press and release: The micrometer will output the displayed data.
 Press and hold: The micrometer will output the displayed data continually unit the button is pressed again.



#### FORK MEASURING COMPANY Vavdi Sr.No. 17, Plot No 55B, Rani Industrial Estate Gondal Road, Rajkot-360002

## **INSTRUCTION MANUAL FOR DIGITAL MICROMETER (601-025)**

#### **Power**

- If the micrometer is not used for five minutes the power will automatically shut off. Powering off the micrometer by pressing the "On/Off-Zero" key to save the battery when not in use is recommended.
- Use a CR2032 battery and replace the battery when the display begins to blur.
- Remove the battery cap by turning it counterclockwise with a coin or the supplied "S" type wrench. Insert a new battery with (+) side up. Replace the battery cap by turning it clockwise.

## **Data Output**

- The output interface is a RS-232C.
- The micrometer can be attached to a PC's USB port by an SPC cable.
- To attach the cable, remove the data output cap and insert the cable. When not using the interface, always keep the data output cap in place.

#### **Precautions**

- Do not subject the instrument to blows or shock. Do not drop it or apply excessive force.
- Do not disassemble the instrument.
- Do not press the keys with a pointed object.
- Do not use or store the instrument under direct sunlight.
- Avoid exposing the instrument away from strong magnetic fields and high voltage.
- Use a soft cloth to clean the instrument. Never use organic solvents such as acetone or benzene to clean.
- · Clean measuring faces before use.
- If the instrument is to be stored or left unused for extended periods, remove the battery.



### FORK MEASURING COMPANY Vavdi Sr.No. 17, Plot No 55B, Rani Industrial Estate Gondal Road, Rajkot-360002

# **INSTRUCTION MANUAL FOR DIGITAL MICROMETER (601-025)**

# **Troubleshooting**

Problem(s)	Cause(s)	Solution(s)
Measuring data incorrect	1.Dirty measuring faces 2.Zero is incorrect	1.Clean measuring faces
No display on LCD	1. Battery position is incorrect	Reset battery     Replace with
<ol> <li>Flickering display</li> <li>Display is sporadic</li> <li>Display remains</li> </ol>	1.Weak battery 2.Weak battery 3.Battery position is	<ol> <li>Replace battery</li> <li>Replace battery</li> <li>Reset battery</li> </ol>
<ol> <li>Display is blurry</li> <li>Output data is</li> </ol>	Weak battery	Replace with new battery